

Imray Correction Notice

24 May 2012

ICE2-1

Chart E2 WGS 84

Edition Jul 2011

Date of printing Jul 2011

The following corrections should be noted:

1 **Isla de Tenerife, north coast**

It should be noted that the north coast of Tenerife is too exposed to permit safe anchoring.

Delete anchorage symbols between Pta Buenavista and Pto de la Cruz (ILNW 450/11)

2 **Waypoints**

The bearing between WP8 and WP13 should read *115°-295° mag 47M*.

The bearing between WP2 and WP1 should read *071°-251° mag 17M*. (ILNW 472/11)

3 **Isla de Hierro, Volcanic Activity**

Volcanic activity has been reported off the coast of Pta Restinga (approx. position 27°36'·5N 18°00'·2W).

Vessels are advised to avoid this area. (ILNW 45/12)

4 **Puerto de San Sebastian de la Gomera (Plan C)**

Insert R spar Lt buoy with rectangular topmk Fl.R.5s in 28°04'·96N 17°06'·76W.

Delete Lt buoy **No1** Fl.R.5s in 28°05'·05N 17°06'·70W (ILNW 224/12)